



ATTENTION !!!

1/2 BROKEN JOINT NOT RECOMMENDED

NO 50%




YES 15%




**THE OVERLAP SHOULD NOT EXCEED 33%
WHEN INSTALLING RECTANGULAR SIZES
IN A STAGGERED BRICK-JOINT PATTERN.**

RECOMMENDED INSTALLATION PATTERNS




STRAIGHT LAY




ALTERNATING FORMAT



1/3 FORMAT



1/4 FORMAT



HERRINGBONE